After trying arming, Rejected by MAV message can be seen on screen...

And why it happens ? Lets go to radio calibration page. There are couple of extra channels with default values -> not possible to calibrate...

We have non used channels with low values... (rc15_Trim and rc16_trim and maby rc13 _trim as well)

So lets change those littlebit...

Go to Config/Tuning and Full parameter list. Search rc15_trim and rc15_min

and give it new values bot trim and min: 1051   (also rc16_min, trim and rc13_min and trim) had to be changed to 1051.

Arming is possible, maby :D